



RADIATION RISK ASSESSMENT NO 31
HAZARD IDENTIFICATION & RISK ASSESSMENT FOR AN INNOVXSYSTEMS X5000 PORTABLE XRF ANALYSER

DESCRIPTION

- 1) The InnovXsystems X5000 is a portable XRF analyser with the x-ray generator and analysis chamber contained within a shielded and interlocked housing. Access to the x-ray beam is not possible during normal operation and can only be achieved by dismantling the x-ray housing and shielding.
- 2) In normal operational use samples are placed in the sample chamber and the enclosure lid must be closed before an exposure can commence. There is no exposure to x-rays when loading samples.
- 3) The x-ray tube operates at 50 kV, 200 μ A. From data supplied in British Standards BS 4094 Part 2: 1971 it is estimated that if the instrument casing were removed and the x-ray tube operated without shielding, unshielded radiation dose rates will be of the order of a few Sv min^{-1} at a distance of 100 mm from the x-ray tube collimator.

<u>Version</u>	<u>Author</u>	<u>Checked</u>	<u>Approved</u>	<u>Date of issue</u>
1.0	ARC	-	ARC	27 th February 2017

It is the reader's responsibility to ensure they hold the current version of this document, which is available from the University Radiation Protection Adviser / Laser Protection Adviser (RPA / LPA). **All previous versions of this document must be destroyed.**

HAZARD & RISK ASSESSMENT

Condition	Exposure pathway	Radiation exposure	Level of risk	Risk reduction measures
Exposure to unshielded x-radiation	External irradiation			
	(1) Damage to, or misalignment of the inherent shielding fitted to the instrument resulting in the leakage of radiation from the cabinet.	<p>Penetrating x-rays; dose rate: Sv min⁻¹.</p> <p>If a person were exposed by standing adjacent to a leakage point, their exposure would exceed an investigation level / dose constraint of 1 mSv in less than a second.</p>	<p>Health – Low</p> <p>The likelihood of the shielding becoming misaligned during normal use is extremely low, and would require severe damage to the instrument.</p> <p>Collateral – Low</p> <p>The unshielded dose rate exceeds internal guidelines and national dose rate limit for the designation of Controlled Areas, and thereby the potential for legislative infraction should there be a failure is very real. However, the likelihood of such a failure is low.</p> <p>Critical failure of the equipment may be reportable to the Health and Safety Executive under RIDDOR.</p>	<p>The x-ray generator and the cabinet enclosure are manufactured to a high standard and are not expected to leak radiation.</p> <p>The equipment has been subject to a ‘Critical Examination’, which found no failings with the system or it’s safety devices.</p> <p>Failure of the x-ray tube or any of the safety features under normal operational conditions would cause the x-ray beam to terminate.</p> <p>The equipment should be checked for leakage using a radiation monitor after being moved to a new location.</p> <p>If the equipment suffers any damage it should not be used before being checked by a qualified service engineer.</p>

Condition	Exposure pathway	Radiation exposure	Level of risk	Risk reduction measures
	<p>(2) Removing the inner instrument casing and overriding the existing engineered safety then gaining access to the x-ray chamber whilst the x-ray tube is generating x-rays and the shutter is open.</p>	<p>Penetrating x-rays; scatter dose rate: Sv h⁻¹ at 1000 mm from the x-ray tube.</p> <p>If a person were standing in front of the instrument with the inner casing removed, their exposure would exceed the investigation level / dose constraint of 1 mSv.</p> <p>Hand accessible dose rates are very high; national limits on extremity exposures would be exceeded in seconds. The dose constraint would be exceeded.</p>	<p>Health – Low</p> <p>It is not possible for a user to easily / inadvertently override the safety features and remove the casing; consequently the risk of exposure through accident or negligence is low.</p> <p>Collateral – Medium</p> <p>The unshielded dose rate exceeds the dose rate limit for the designation of Controlled Areas, and thereby the potential for legislative infraction, should a person deliberately by-pass the safety systems, is real.</p>	<p>Users must be trained in the operation of the equipment and must follow appropriate protocols.</p> <p>No one should attempt to bypass any of the safety features or dismantle the equipment.</p>

Condition	Exposure pathway	Radiation exposure	Level of risk	Risk reduction measures
Damage / fire				
	Damage to the equipment by fire.	<p>Penetrating x-rays; dose rate: Sv min⁻¹.</p> <p>If the equipment was damaged but still operable, and a person was exposed by standing adjacent to a leakage point, their exposure would exceed the investigation level / dose constraint of 1 mSv.</p>	<p>Health - Low</p> <p>If the equipment were subject to high-energy impact there is the low possible that misalignment might occur.</p> <p>It is unlikely that the equipment would remain operable after sustaining fire damage.</p>	If the equipment has received a significant knock, has been close to a fire, or has been damaged in any other way the user should (1) switch off and isolate the power, then (2) inform the RPS, the RPM to seek advice before using the equipment.
Unauthorised maintenance / servicing				
	Unauthorised maintenance/repair leading to access to an unguarded x-ray beam.	<p>Penetrating x-rays; dose rate: Sv min⁻¹.</p> <p>Hand accessible dose rates are very high; national limits on extremity exposures would be exceeded in a few seconds.</p>	<p>Health – High</p> <p>Dismantling of the instrument could give access to areas where there is a high dose rate.</p> <p>Collateral – Medium</p> <p>Dose rate exceeds internal guidelines and national dose rate limit for the designation of Controlled Areas; potential for legislative infraction.</p>	<p>All repairs and modifications to the equipment must only be carried out by the manufacturer or by a qualified service engineer approved by the RPS.</p> <p>If the equipment is serviced on site the service engineer must have sole use of the area.</p>